

ببمودة بثقة  
Moving Forward  
with Confidence



To:

**THE DIRECTOR GENERAL OF HEALTH SERVICES IN ALL GOVERNORATES**  
**Commanding Officer, Armed Forces Hospital (Al Khoudh & Salalah)**  
**Director General of Engineering Affairs, MOH**  
**Director General of Royal Hospital**  
**Director General of Khoula Hospital**  
**Director General of Medical Supplies (MOH)**  
**Director General of Pvt. Health Est. Affairs (to kindly arrange distribution to all Pvt. Hospitals)**  
**Hospital Director (Al Nahda Hospital)**  
**Hospital Director (Al Massara Hospital)**  
**The Head of Medical Services in SQU Hospital**  
**The Head of Medical Services in Royal Oman Police**  
**The Head of Medical Services in Ministry of Defence**  
**The Head of Medical Services in The Diwan**  
**The Head of Medical Services in The Sultan's Special Force**  
**The Head of Medical Services in Internal Security Services**  
**The Head of Medical Services in Petroleum Development of Oman**  
**The Head of Medical Services in LNG Oman**  
**ALL PRIVATE PHARMACIES & DRUG STORES**

After Compliments,

Please find attached our Circular No 209 dated 20/11/2022 Regarding NCMDR  
FSCA of Alinity m System from (mfr: Abbott).

Copy to:

- Director, Office of H.E. The Undersecretary for Health Affairs
- Director of Medical Device Control, DGPA&DC
- Director of Pharmacovigilance & Drug Information Dept, DGPA&DC
- Director of Drug Control Department, DGPA&DC
- Director of Pharmaceutical Licensing Department, DGPA&DC
- Director of Central Quality Control Lab., DGPA&DC
- Supdt. of Central Drug Information



**PADDC**  
المديرية العامة للصيدلة والرقابة الدوائية  
Directorate General of Pharmaceutical  
Affairs & Drug Control



ص.ب: ٣٩٣ مسقط - الرمز البريدي: ١٠٠ - هاتف: ٢٢٣٥٧١١١ - فاكس: ٢٢٣٥٨٤٨٩

P.O. Box: 393 Muscat - Postal Code : 100 - Tel: 22357111 - Fax: 22358489

🐦 dgpa\_dc Email: dg-padcc@moh.gov.om



Circular No. 209/2022


26 -04-1444 H

20 -11-2022

ببمقدار ثقة  
Moving Forward  
with Confidence



### Field Safety Corrective Action of Alinity m System from Abbott

|                       |  |
|-----------------------|--|
| Source                | NCMDR- National Center for Medical Devices Reporting- SFDA<br><a href="https://ncmdr.sfda.gov.sa/Secure/CA/CaViewRecall.aspx?caid=4&amp;rid=17312">https://ncmdr.sfda.gov.sa/Secure/CA/CaViewRecall.aspx?caid=4&amp;rid=17312</a>  |
| Product               | Alinity m System.  |
| Description           | IVD.   |
| Manufacturer          | Abbott.  |
| Local agent           | Waleed Pharmacy & Stores LLC.  |
| The affected products | List Number: 08N53-002<br>Unique Device Identifier (UDI): 00884999048034.  |
| Reason                | Four potential performance issues.   |
| Action                | 1. Please refer to "Appendix A" in the attached FSN for available actions until your Alinity m System receives the software upgrade.<br>2. Contact the local agent for remedial action.  |
| Product image         |    |
| comments              | Healthcare professionals are encouraged to report any adverse events Suspected to be associated with the above device or any other medical device to Department of Medical Device Control through the E-mail: <a href="mailto:Med-device@moh.gov.om">Med-device@moh.gov.om</a> |

Dr. Mohammed Hamdan Al-Rubaie

Director General





**Urgent Field Safety Notice**  
**Molecular Diagnostics at Abbott**  
**Product: Alinity m System**  
**List Number: 08N53-002**  
**Not Serial Specific**  
**Unique Device Identifier (UDI): 00884999048034**

October 14, 2022

Dear Abbott Customer,

This letter contains important information regarding your Alinity m System; specifically, the current software installed on your Alinity m System. Please review this information carefully.

**Background**

Abbott has identified four potential performance issues for the Alinity m System Software and will release an updated Alinity m System Software version to correct these issues (see details in **Appendix A**).

1. In a unique scenario, the waste chute flapper was found to not open when the Systems Solution drawer was closed and locked.
2. Sample preparation drawer #1 barcode information is used instead of sample prep drawer #2 when the scanned data is not sent to the System Control Center before the next bottle barcode in sample prep drawer#2 is scanned.
3. Under a specific condition, while the system is processing tests and a new test request is made, when the level of the bulk solution is too low to process a test, the software would error stop the system and try to complete all in-process tests.
4. 4 to 6 replicates of the same auto calibrator orders can be run with 2 different sets of calibrator materials on the same rack. It was discovered during internal testing, when running 4 to 6 replicates of a calibrator, it is possible for the user to use 2 separate lots of material which is not detected by the System Control Center (SCC).

**Potential Impact**

Refer to **Appendix A** for details concerning any hazards identified due to the issues found in the Alinity m System software

**Necessary Actions**

Please refer to **Appendix A** for available actions until your Alinity m System receives the software upgrade. Please review this information with laboratory personnel and retain this communication for future reference.

Your Abbott representative will schedule a mandatory upgrade of your Alinity m Series software. Anticipated release of the software update is scheduled for the end of October 2022. Software will be available upon local regulatory approval.

Please complete and return the Customer Reply Form.



Abbott  
1300 E. Touhy Ave.  
Des Plaines, IL 60018

**Urgent Field Safety Notice  
Molecular Diagnostics at Abbott**

**Product:** Alinity m System

**List Number:** 08N53-002

**Not Serial Specific**

**Unique Device Identifier (UDI):** 00884999048034

If you have any questions regarding this communication, please contact your local Abbott representative. We apologize for any inconvenience this may have caused your laboratory.

Sincerely,

*Albert Chianello Oct 14, 2022*

Albert Chianello  
Director, Quality Assurance  
Molecular Diagnostics at Abbott



Abbott  
1300 E. Touhy Ave.  
Des Plaines, IL 60018

**Urgent Field Safety Notice  
Molecular Diagnostics at Abbott**

**Product:** Alinity m System

**List Number:** 08N53-002

**Not Serial Specific**

**Unique Device Identifier (UDI):** 00884999048034

**Appendix A**

| Alinity m System |   |   |  |
|------------------|---|---|--|
|                  | Issue   | Hazards and Impact  | Available Actions Until Mandatory Upgrade is Complete  |
| 1.               | Flapper door does not open when Bulk Fluidics drawer was closed. It was found that the software will cause the flapper door to stay in the closed position when the drawer is closed and locked if the flapper had previously been moved out of position. | There is the potential for incorrect results if overflow of the tips or reaction vessels cause contamination in the instrument. There is also the potential of a biohazard exposure during clean-up of any build of tips or reaction vessels that fall outside the waste container.   | This occurrence was only found in-house under non-standard operating conditions. Prior to instrument use, empty waste container. If waste overflow occurs, please follow internal bio-hazardous waste cleaning procedures.   |
| 2.               | Sample preparation (prep) drawer #1 barcode information is used instead of sample prep drawer #2.   | There is the potential for delay in results when two different Alinity m assay types are run (RNA/DNA). The SCC may receive the information from drawer 1 (RNA assay) as the data for drawer #2 (DNA assay) resulting in internal control failure. There is also the potential for incorrect results if two different lots are used when running an Alinity m quantitative assay. Specifically, when the SCC receives the information from drawer #1 (lot A) as the data for drawer #2 (lot B), results would be generated using the wrong calibration curve potentially causing incorrect results. | To help mitigate potential occurrence, the following can be done:<br>1) Verify that only ONE lot of sample prep kit material is on the system at a time.<br>2) Load one sample prep drawer at a time. Once the first drawer is scanned, verify the scanned information is correct on the SCC. After drawer 1 information has been verified to be correct, load the second drawer. After scanning, verify the correct information for drawer 2 is correct on the SCC. |



Abbott  
 1300 E. Touhy Ave.  
 Des Plaines, IL 60018

**Urgent Field Safety Notice  
 Molecular Diagnostics at Abbott**

**Product:** Alinity m System

**List Number:** 08N53-002

**Not Serial Specific**

**Unique Device Identifier (UDI):** 00884999048034

|    | <b>Issue</b>   | <b>Hazards and Impact</b>  | <b>Available Actions<br/>Until Mandatory<br/>Upgrade is Complete</b>   |
|----|--|--|--|
| 3. | Instrument Embedded Controller (IEC): Error stopping due to low level of bulk reagents when a test order is received. When this occurs, an internal counter is reset which can cause RVs already present in Amp Detect Unit (ADU) to remain there and not be moved to waste. If the RVs are not removed and new RVs are transferred into the ADU, the RVs would "double stack" such that that the amp detect could error causing the system to not run when restarted. | In the worst-case scenario of the RV stacking scenario, FSE may be required to visit the customer site to remediate an event. This may cause a potential delay in results.   | Take the module out of service per M&D 2752 or clean out the amp detect RVs via M&D 1401, Contact your Abbott representative for further guidance. |
| 4. | 4 to 6 replicates of the same auto calibrator orders can be run with 2 different sets of calibrator materials on the same rack. If this were to occur, the calibration curve would be created using 2 separate material lots. In normal use scenario, this curve would be made using only 1 lot of material.   | There is a potential for delay in results if 2 different sets of materials are used to calibrate. The calibration would need to be reran to obtain a valid curve. There is also the potential of incorrect results. The curve generated with 2 different material lots could potentially generate incorrect results. | If loading 2 or more tubes of calibrator material, verify that they are from the same lot.   |