وزارة الصحة
Ministry of Health

**To:**

**THE DIRECTOR GENERAL OF HEALTH SERVICES IN ALL GOVERNORATES**
**Commanding Officer, Armed Forces Hospital (Al Khoudh & Salalah)**
**Director General of Engineering Affairs, MOH**
**Director General of Royal Hospital**
**Director General of Khoula Hospital**
**Director General of Medical Supplies (MOH)**
**Director General of Pvt. Health Est. Affairs (to kindly arrange distribution to all Pvt. Hospitals)**
**Hospital Director (Al Nahda Hospital)**
**Hospital Director (Al Massara Hospital)**
**The Head of Medical Services in SQU Hospital**
**The Head of Medical Services in Royal Oman Police**
**The Head of Medical Services in Ministry of Defence**
**The Head of Medical Services in The Diwan**
**The Head of Medical Services in The Sultan's Special Force**
**The Head of Medical Services in Internal Security Services**
**The Head of Medical Services in Petroleum Development of Oman**
**The Head of Medical Services in LNG Oman**
**ALL PRIVATE PHARMACIES & DRUG STORES**

**After Compliments,**

**Please find attached our Circular No 115 dated 18 /11/2026.**

**Copy to:**

- **Director, Office of H.E. The Undersecretary for Health Affairs**
- **Director of Medical Device Department, DSC**
- **Director of Pharmacovigilance Department, DSC**
- **Director of Medicine Registration Department, DSC**
- **Director of Regulatory Compliance Department, DSC**
- **Director of Central Quality Control Lab., DSC**
- **Supdt. of Central Drug Information**

P.O. Box 393, Postal Code 100, Muscat, Sultanate of Oman, Tel: +968 22357628, +968 22357111, Email: dscpho@moh.gov.om

وزارة الصحة
Ministry of Health
Sultanate of Oman سلطنة عمان

# Circular No. 115 / 2026

08-06-1448 H
18-11-2026

**Recall of Disposable Syringe 5ml/cc from Jiangsu Eyoung Medical Devices Co.,Ltd.**

| | |
|---|---|
| Product | Disposable Syringe 5ml/cc |
| Manufacturer | Jiangsu Eyoung Medical Devices Co., Ltd. |
| Local Agent | Mutrah Pharmacy LLC. |
| The affected products | Batch No.: 20241105. |
| Reason | Following reported complaints received from local healthcare institutions regarding failure to maintain negative pressure during blood collection, resulting in air entrapment and insufficient blood sample collection, the manufacturer's investigation identified reduced elasticity of the rubber stopper, causing improper engagement with the syringe plunger.<br>The investigation concluded that this batch has the problem of no negative pressure due to the gasket problem of that particular batch. |
| Action | 1. Identify, quarantine and return the affected devices.<br>2. Contact the local agent for remedial action. |
| comments | Healthcare professionals are encouraged to report any adverse events Suspected to be associated with the above device or any other medical device to Department of Medical Device Control through the E-mail: vigilance-md@moh.gov.om |

A/ **Ph. Ibrahim Nasser Al Rashdi**
**Director General**

سلطنة عمان - وزارة الصحة
مركز سلامة الدواء
SULTANATE OF OMAN - MINISTRY OF HEALTH
DRUG SAFETY CENTER

P.O. Box 393, Postal Code 100, Muscat, Sultanate of Oman, Tel: +968 22357628, +968 22357111, Email: dscpho@moh.gov.om