Sultanate of Oman Ministry of Health Drug Safety Center Muscat



سلطنة عُمان وزارة الصحة مركز سلامة الدواء مسقط

To:

THE DIRECTOR GENERAL OF HEALTH SERVICES IN ALL GOVERNORATES

Commanding Officer, Armed Forces Hospital (Al Khoudh & Salalah)

Director General of Engineering Affairs, MOH

Director General of Royal Hospital

Director General of Khoula Hospital

Director General of Medical Supplies (MOH)

Director General of Pvt. Health Est. Affairs (to kindly arrange distribution to all Pvt. Hospitals)

Hospital Director (Al Nahda Hospital)

Hospital Director (Al Massara Hospital)

The Head of Medical Services in SQU Hospital

The Head of Medical Services in Royal Oman Police

The Head of Medical Services in Ministry of Defence

The Head of Medical Services in The Diwan

The Head of Medical Services in The Sultan's Special Force

The Head of Medical Services in Internal Security Services

The Head of Medical Services in Petroleum Development of Oman

The Head of Medical Services in LNG Oman

ALL PRIVATE PHARMACIES & DRUG STORES

After Compliments,

Please find attached our Circular No 155 dated 4/11/2024 Regarding Field Safety Corrective Action of OmniWire Pressure Guide Wire Internal Wire from (mfr: Philips).

Copy to:

- Director, Office of H.E. The Undersecretary for Health Affairs
- Director of Medical Device Control, DSC
- Director of Pharmacovigilance & Drug Information Dept, DSC
- Director of Drug Control Department, DSC
- Director of Pharmaceutical Licensing Department, DSC
- Director of Central Quality Control Lab., DSC
- Supdt. of Central Drug Information





Sultanate of Oman Ministry of Health Drug Safety Center Muscat



سلطنة عُمــان وزارة الصحــة مركز سلامة الــدواء مسقط

Circular No. \55/2024

02 -051446 H 04-11-2024

Field Safety Corrective Action of OmniWire Pressure Guide Wire Internal Wire from Philips.

Source	Philips through their local distributor Nexhold Medical Supply LLC.
Product	OmniWire Pressure Guide Wire Internal Wire.
Manufacturer	Philips.
Local agent	Nexhold Medical Supply LLC.
The affected products	All OmniWire Pressure Guide Wires manufactured since February 2022 (2022-02-01) are potentially impacted.
Reason	Internal wire component could become damaged due to the wire potentially not meeting an internal specification.
Action	 Continued use of the OmniWire Pressure Guide Wire should be according to the Instructions for Use (IFU). If any loss of signal were to occur during use, replace the wire with another OmniWire to complete the procedure. If you experience any signal issues when using the OmniWire, please notify your local distributor so that they can file a complaint and request for replacements.
comments	Healthcare professionals are encouraged to report any adverse events Suspected to be associated with the above device or any other medical device to Department of Medical Device Control through the E-mail: vigilance-md@moh.gov.om

44

Dr Mohammed Hamdan Al Rubaic Director General





